

STATUS OF CLOSED / ABANDONED MINES

| SL. NO. | Item | No | %age | No | %age | No | %age | No | %age | No | %age | No | %age | No | %age | No | %age |
|---------|--|-----|------|------|------|-----|------|-----|------|------|------|-----|------|-----|---|-----|------|
| 1 | COMPANY | ECL | | BCCL | | CCL | | WCL | | SECL | | MCL | | NCL | | NEC | |
| 2 | TOTAL NOS. OF ABANDONED OPENINGS AND QUARRIES | | | | | | | | | | | | | | 1(One) OC mine is abandoned with 3 voids filled with water. Mine was closed in 1997 | | |
| 3 | TOTAL UG MINE OPENINGS FOR CLOSURE | | | | | | | | | | | | | | NA | | |
| 4 | UG openings sealed | | | | | | | | | | | | | | NA | | |
| 5 | UG mines in which pumping is going on | | | | | | | | | | | | | | NA | | |
| 6 | TOTAL QUARRIES (OC) FOR CLOSURE | | | | | | | | | | | | | | 1 | | |
| 7 | Quarries already backfilled(OC) | | | | | | | | | | | | | | Except 3 voids, area is backfilled | | |
| 8 | Quarries partially backfilled(Target date of completion) | | | | | | | | | | | | | | NA | | |
| 9 | Quarries where backfilling is in progress (Target date of completion) | | | | | | | | | | | | | | nil | | |
| 10 | Quarries yet to be backfilled (Target date of completion) | | | | | | | | | | | | | | 3 voids in one mine (filled with acidic water) | | |
| 11 | Quarries serving as water reservoirs | | | | | | | | | | | | | | 3 voids | | |
| 12 | Quarry on fire : Fire Quenching in progress | | | | | | | | | | | | | | nil | | |
| 13 | Illegal mining sites | | | | | | | | | | | | | | nil | | |
| 14 | Total OC | | | | | | | | | | | | | | 1 | | |

| |
|-------------|
| %age |
|-------------|

| |
|-----|
| CIL |
|-----|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|