



LIST of QUARTERS REPAIRED AT NSC, JAYANT

S.N.	Qtr. No.	Nature of Repair (Major Work done)	Date of Completion
1	MQ-20	1. Floor & Wall Tiles in Bathroom & WC 2. Kota Stone Slab flooring in Kitchen platform and Wall Tiles 600 mm above Kitchen Platform 3. Steel Kitchen Sink 4. Wash Basin, Tower Rail, Mirror, Glass Shelf 5. Distempering inside Qtr. 6. Exterior Painting 7. Orissa Pan in WC 8. Replacement of Damaged Water Supply Pipe Line in bathroom & WC	23.06.2016
2	MQ-22	-Do-	23.06.2016
3	MQ-49	-Do-	26.06.2016
4	MQ-50	-Do-	27.06.2016
5	MQ-53	-Do-	27.06.2016
6	MQ-52	-Do-	27.06.2016
7	MQ-51	-Do-	01.07.2016
8	MQ-92	-Do-	01.07.2016
9	MQ-21	-Do-	01.07.2016
10	MQ-24	-Do-	03.07.2016
11	MQ-25	-Do-	07.07.2016
12	MQ-44	-Do-	11.07.2016
13	MQ-57	-Do-	13.07.2016
14	MQ-58	-Do-	15.07.2016
15	MQ-61	-Do-	18.07.2016
16	MQ-62	-Do-	20.07.2016
17	MQ-63	-Do-	22.07.2016
18	MQ-65	-Do-	25.07.2016
19	MQ-64	-Do-	25.07.2016
20	MQ-66	-Do-	28.07.2016
21	MQ-67	-Do-	28.07.2016
22	MQ-68	-Do-	04.08.2016
23	MQ-69	-Do-	05.08.2016
24	MQ-70	-Do-	06.08.2016
25	MQ-71	-Do-	08.08.2016
26	MQ-72	-Do-	08.08.2016
27	MQ-73	-Do-	09.08.2016
28	MQ-75	-Do-	10.08.2016
29	MQ-79	-Do-	11.08.2016
30	MQ-81	-Do-	12.08.2016
31	MQ-82	-Do-	13.08.2016
32	MQ-84	-Do-	20.08.2016
33	MQ-85	-Do-	22.08.2016
34	MQ-87	-Do-	24.08.2016
35	MQ-88	-Do-	26.08.2016
36	MQ-01	-Do-	29.08.2016
37	MQ-08	-Do-	30.08.2016
38	MQ-27	-Do-	31.08.2016
39	MQ-28	-Do-	01.09.2016
40	MQ-59	-Do-	02.09.2016
41	MQ-60	-Do-	03.09.2016
42	MQ-33	-Do-	05.09.2016
43	MQ-34	-Do-	05.09.2016
44	MQ-30	-Do-	10.09.2016
45	MQ-31	-Do-	10.09.2016
46	MQ-45	-Do-	12.09.2016
47	MQ-46	-Do-	13.09.2016
48	MQ-04	-Do-	14.09.2016
49	MQ-39	-Do-	15.09.2016
50	MQ-32	-Do-	16.09.2016

51	MQ-36	-Do-	17.09.2016
52	MQ-41	-Do-	19.09.2016
53	MQ-18	-Do-	20.09.2016
54	MQ-94	-Do-	21.09.2016
55	MQ-95	-Do-	22.09.2016
56	MQ-96	-Do-	23.09.2016
57	MQ-74	-Do-	24.09.2016
58	MQ-91	-Do-	26.09.2016
59	MQ-43	-Do-	27.09.2016
60	MQ-23	-Do-	27.09.2016
61	MQ-10	-Do-	29.09.2016
62	MQ-76	-Do-	30.09.2016
63	MQ-13	-Do-	09.10.2016
64	MQ-48	-Do-	12.10.2016
65	MQ-17	-Do-	15.10.2016
66	MQ-47	-Do-	19.10.2016
67	MQ-26	-Do-	20.10.2016
68	MQ-55	-Do-	21.10.2016
69	MQ-93	-Do-	22.10.2016
70	MQ-03	-Do-	01.11.2016
71	MQ-07	-Do-	02.11.2016
72	MQ-12	-Do-	03.11.2016
73	MQ-14	-Do-	04.11.2016
74	MQ-86	-Do-	05.11.2016
75	MQ-54	-Do-	08.11.2016
76	MQ-16	-Do-	21.11.2016
77	MQ-37	-Do-	22.11.2016
78	MQ-29	-Do-	23.11.2016
79	MQ-19	-Do-	24.11.2016
80	MQ-56	-Do-	29.11.2016
81	MQ-02	-Do-	30.11.2016
82	MQ-35	-Do-	25.11.2016
83	MQ-09	-Do-	26.11.2016.
84	MQ-15	-Do-	28.11.2016
85	MQ-05	-Do-	22.02.2017
86	MQ-06	-Do-	17.02.2017
87	MQ-38	-Do-	17.02.2017
88	MQ-40	-Do-	26.04.2017
89	B-53	1. Floor & Wall Tiles in Bathroom & WC 2. Kota Stone Slab flooring in Kitchen platform and Wall Tiles 600 mm above Kitchen Platform 3. Steel Kitchen Sink 4. Distempering inside Qtr. 5. Exterior Painting 6. Orissa Pan in WC 7. Replacement of Damaged Water Supply Pipe Line in bathroom & WC	28.06.2016
90	B-47	-Do-	29.06.2016
91	B-24	-Do-	29.06.2016
92	B-26	-Do-	29.06.2016
93	B-36	-Do-	04.07.2016
94	B-38	-Do-	05.07.2016
95	B-25	-Do-	05.07.2016
96	B-41	-Do-	30.07.2016
97	B-39	-Do-	01.08.2016
98	B-65	-Do-	02.08.2016
99	B-60	-Do-	02.08.2016
100	B-70	-Do-	03.08.2016
101	B-69	-Do-	03.08.2016
102	B-31	-Do-	16.08.2016
103	B-08	-Do-	17.08.2016
104	B-19	-Do-	19.08.2016
105	B-40	-Do-	18.08.2016

106	B-29	-Do-	07.09.2016
107	B-55	-Do-	01.10.2016
108	B-20	-Do-	03.10.2016
109	B-43	-Do-	04.10.2016
110	B-35	-Do-	05.10.2016
111	B-14	-Do-	24.10.2016
112	B-22	-Do-	25.10.2016
113	B-03	-Do-	09.11.2016
114	B-21	-Do-	10.11.2016
115	B-27	-Do-	11.11.2016
116	B-28	-Do-	12.11.2016
117	B-09	-Do-	12.11.2016
118	B-12	-Do-	14.11.2016
119	B-32	-Do-	15.11.2016
120	B-54	-Do-	01.12.2016
121	B-56	-Do-	02.12.2016
122	B-04	-Do-	05.12.2016
123	B-05	-Do-	06.12.2016
124	B-06	-Do-	07.12.2016
125	B-62	-Do-	08.12.2016
126	B-66	-Do-	09.12.2016
127	B-59	-Do-	10.12.2016
128	B-49	-Do-	10.12.2016
129	B-45	-Do-	12.12.2016
130	B-67	-Do-	13.12.2016
131	B-61	-Do-	14.12.2016
132	B-63	-Do-	15.12.2016
133	B-16	-Do-	16.12.2016
134	B-58	-Do-	17.12.2016
135	B-30	-Do-	18.12.2016
136	B-33	-Do-	19.12.2016
137	B-64	-Do-	20.12.2016
138	B-37	-Do-	21.12.2016
139	B-57	-Do-	22.12.2016
140	B-68	-Do-	08.02.2017
141	B-50	-Do-	10.02.2017
142	B-42	-Do-	12.02.2017
143	B-52	-Do-	14.02.2017
144	B-51	-Do-	16.02.2017
145	B-10	-Do-	16.02.2017
146	B-11	-Do-	18.02.2017
147	B-15	-Do-	22.02.2017
148	B-02	-Do-	14.03.2017
149	B-44	-Do-	16.03.2017
150	C-17	1. Floor & Wall Tiles in Bathroom & WC 2. Wall Tiles 600 mm above Kitchen Platform 3. Steel Kitchen Sink 4. Orissa Pan & European WC in Toilet 5. Replacement of Damaged Water Supply Pipe Line in bathroom & WC	08.10.2016
151	C-07	-Do-	11.10.2016
152	C-09	-Do-	14.10.2016
153	C-24	-Do-	18.10.2016
154	C-10	-Do-	26.10.2016
155	C-02	-Do-	27.10.2016
156	C-15	-Do-	29.10.2016
157	C-03	-Do-	26.12.2016
158	C-04	-Do-	29.12.2016
159	C-05	-Do-	31.12.2016
160	C-27	-Do-	03.01.2017
161	C-30	-Do-	06.01.2017
162	C-34	-Do-	09.01.2017

163	C-45	-Do-	12.01.2017
164	C-46	-Do-	16.01.2017
165	C-44	-Do-	19.01.2017
166	C-47	-Do-	20.01.2017
167	C-48	-Do-	21.01.2017
168	C-33	-Do-	23.01.2017
169	C-36	-Do-	24.01.2017
170	C-08	-Do-	18.02.2017
171	C-19	-Do-	14.02.2017
172	C-22	-Do-	14.04.2017
173	C14	-Do-	17.04.2017
174	C-11	-Do-	20.04.2017
175	C-40	-Do-	21.04.2017
176	C-01	-Do-	25.04.2017
177	D-01	1. Floor & Wall Tiles in Bathroom & WC 2. Granite Stone flooring in Kitchen platform and Wall Tiles 600 mm above Kitchen Platform 3. Steel Kitchen Sink 4. Orissa Pan & European WC in Toilet 5. Replacement of Damaged Water Supply Pipe Line in bathroom & WC	22.06.2016
178	D-02	-Do-	26.06.2016
179	D-07	-Do-	26.01.2017
180	D-05	-Do-	31.01.2017
181	D-06	-Do-	05.02.2017